US ERA ARCHIVE DOCUMENT

UNIT LOG		Incident Name		2. Date Prepared	3. Time Prepared	
		Kalamazoo River/Enbridg	e Oil Spill	12/11/2012	1700	
4. Unit Name/Designators Situation Unit		5. Unit Leader (Name and Position)			6. Operational Period	
		Melinda Luetke, Planning Section Chief		0700, 12/10/2012 - 0700, 12/22/2012		
7.		Pe	rsonnel Rost	er Assigned	10:00, 12:22:20:2	
	Name		Position		Home Base	
	Matthew Haak	Situation	Unit Leader		Houston	
3.		Λοι	tivity Log			
Time		ACI	tivity Log Major Events	3		
0800	· Attende	ed the internal C&G meeting				
0900	· Arrived	Arrived at C0.4 Boat launch.				
	· MP5.63	MP5.63 LDB ice observed forming above the railroad trestles				
	• MP5.63 LDB ice observed forming below the railroad trestles					
	 MP5.63 LDB below the railroad trestles no sheen observed. 					
	Ceresco Dam impoundment observed a bathymetry team					
	• MP5.63 – MP5.70 RDB observed ice forming					
	· MP5.63 RDB sheen observed					
	· MP5.55	• MP5.55 RDB observed ice forming above the railroad trestles				
	• Observe	Observed a crew decanting and sampling the CSDs				
	· Observe	· Observed core logging				
	· MP12.5	• MP12.5 LDB observed an RI crew				
	· MP15.2	MP15.25 South Mill Pond observed ice forming, no sheen observed.				
	· MP10.5	MP10.5 LDB Sediment Trap observed ice forming				
	• MP10.4	· MP10.4 RDB Sediment Trap observed ice forming				
		 Morrow Lake observed a sweep boat operating, no sheen observed in the north or south coves. 				
	· MP36.5 RDB no sheen observed.					
	MP21.5 Sediment trap observed a bathymetry team					
	· MP19.2	MP19.25 Sediment trap observed a bathymetry team				
1600	Returned to ICP.					

Matthew Haak, Situation Unit Leader, USEPA-START